

File Ref #:4956127

Inspection No.15408726 Inspection Date: August 30, 2022

Report of Workplace Inspection

Inspectee: THE GOVERNORS OF ST. FRANCIS XAVIER UNIVERSITY

Operating As: ST. FRANCIS XAVIER UNIVERSITY

Mailing Address: 4130 University Avenue

Antigonish, Nova Scotia B2G 2W5

Worksite Location: 42 West Street

Antigonish, NS B2G 1R8

Non-Management Rep: Dean Delaney

Occupation: Painter

Management Rep: Vince Arsenault
Occupation: Buildings Supervisor

Inspection Overview:

On Wednesday August 30, 2022, Officer Henshaw and Officer Dobson conducted an inspection at the above-mentioned workplace.

The workplace is a maintenance project to an existing structure where the wooden window frames were being scrapped and re-painted. The structure is a 3 storey brick apartment building with a flat roof. There were 6 employees on site.

All employees involved with this inspection were co-operative with the officers.

Please note that this inspection is not comprehensive and that it is still the responsibility of the employer to ensure the health and safety of all those persons at or near the workplace.

Inspection Findings:

1. Workplace Health and Safety Regulations

General Overview

1. The officer observed the employees without fall protection. Fall protection must be utilized in an area where fall protection is required (WARNING). The employer attempted to install guardrail as a means of fall protection but the single light barricade

Inspection No.15408726 Inspection Date: August 30, 2022

Report of Workplace Inspection

Inspectee: THE GOVERNORS OF ST. FRANCIS XAVIER UNIVERSITY

Operating As: ST. FRANCIS XAVIER UNIVERSITY

used was insufficient.

2. There was an elevating work-platform at the workplace that was inspected daily before each use and fall-arrest equipment was worn and anchored to a suitable anchorage.

Warnings:

- 1. Workplace Health and Safety Regulations
 - 21.5-3 Guardrails

If there is a risk of falling at a doorway or the opening of a building floor, roof, walls or shaft, an employer must ensure that a guardrail is

- (a) installed in accordance with this Section; and
- (b) marked with a warning sign that indicates the presence of a doorway or other opening.

There was no guardrail installed at the workplace where required. Guardrails must be designed and installed in compliance with the latest version of CSA standard CSA Z797.

This inspection i	report was provided to	by:
Officer Name:	David Henshaw	
Officer Signatu	re:	
This report was may be contacte	produced by David Henshaw, Occupational Health and Saf d at:	fety Officer, who

Occupational Health and Safety Division Department of Labour, Skills and Immigration 187 Terra Cotta Dr

New Glasgow, NS B2H 6B6

Phone: 1-800-952-268 Fax: 902-755-3158 Email: David.Henshaw@novascotia.ca

Inspection No.15408726 Inspection Date: August 30, 2022

Report of Workplace Inspection

Inspectee: THE GOVERNORS OF ST. FRANCIS XAVIER UNIVERSITY

Operating As: ST. FRANCIS XAVIER UNIVERSITY

Within Nova Scotia, call: 1-800-952-2687 Fax: 902-541-5651

Outside Nova Scotia, call: 902-424-5400

Section 69 of the Occupational Health and Safety Act allows orders and some decisions to be appealed. You may appeal this order by filing notice with the Labour Board no later than 30 days after being served this notice. To get information and the required forms, please visit the Labour Board website at: http://www.novascotia.ca/lae/labourboard/.

Contraventions of the OHS Act and regulations can result in administrative penalties being issued. Compliance with orders issued by OHS officers is expected and required by law; it does not prevent a penalty from being issued.